

Project: Alaska Copper	Works		Inspect	ion Date:	1/16/20	
Project No.: 19ACW1			Te	chnician:	Elaine Lytle	
System Performance:						
Was system running during the	inspection? 🛛 Yes	□ No				
Flow Rates (gpm)	Influent 205.2	Effluent _	145	The flows sh	ould be ~155 gpm	
Bag Filter #1 Pressures (psi)	Influent 20	Effluent _		_	ers should be replac Il pressure > 8 psi	ced
Bag Filter #2 Pressures (psi)	Influent 20	Effluent _	16	ii dillerentia	ii pressure > 6 psi	
Carbon Filter Pressures (Lead)	Influent 10	Effluent _			filters should be if differential	
Carbon Filter Pressures (Lag)	Influent 3	Effluent _	_	pressure > 8		
Were the bag filters replaced?	☐ Yes ☒ No					
Was the carbon backflushed?	☐ Yes 🖾 No					

Maintenance and Inspection Checklist:

Task	Completed (Y/N)	Issues/Notes/Comments
Walchem Controller Inspected	⊠ Yes □ No	No issues
Flow Meters Inspected	⊠ Yes □ No	Reading properly
Level Sensor Cleaning/Inspection	⊠ Yes □ No	Reading properly
Inspect System Plumbing	⊠ Yes □ No	No leaks
Pumps Inspected	⊠ Yes □ No	Running propperly
General Housekeeping	⊠ Yes □ No	Clean other than used cartridge filters on ground
Chemistry Level	⊠ Yes □ No	1 full 55 gallon drum, one empty
Safety Materials Inspected	⊠ Yes □ No	All there in job box
pH Probe Inspection/Calibration	⊠ Yes □ No	Verified. Raw water reading 7.63.



Gibout III.

W	a	te	r	Sa	m	p	lin	g:

Tracer Sampling.					
Were water samples taken?					
Raw water:	рН	6.88	Turbidity	16.3	NTU
Bag Filter Influent pH		7.68	Turbidity	12.4	NTU
Bag Filter Effluent	рН	8.02	Turbidity	11.1	NTU
Carbon Filter Influ	ent pH	7.23	Turbidity	8.68	NTU
Carbon Filter Efflu	ent pH	6.73	Turbidity	7.47	NTU
Monthly Tasks:					
Were samples sub	mitted to	Analytical?	'□Yes 🖾 N	lo	
Analytical Lab: N	<u>'A</u>				
Was Walchem data downloaded? ☐ Yes 🗵 No					
Were the tank sludge levels checked? ☐ Yes 🖾 No					
Sludge Depth (inches):					
Decant Tank:	N/A				
Treatment tank:	N/A				
Backflush tank:	N/A				
Main lift station:	N/A				
North lift station:	N/A				
South lift station:	N/A				

Additional Comments, Recommendations and System Upsets:

Took out of freeze protection. All three lift stations were running.

Elaine Lytle	Water Treatment Tech	1/16/20
Technician	Title	Date

Submit

Page 2 of 2